



# Cutting Speeds

50 Cycles




60 Cycles



50

# Approximate values for cutting speed – Cutting angle – Lubricant



Values valid for dry cutting with:

High - speed steel tools for cutting speed  $v_{60}$  ( age 60min.)

Carbon tipped tools for cutting speed  $v_{240}$  (age 240min.)

Side angle  $\chi = 45^\circ$ , point angle  $\xi = 90^\circ$ , angle of inclination

$\lambda = 0 \dots 8^\circ$ ,

for light alloy and plastic  $\lambda = 5 \dots 10^\circ$ .

Cutting speed

These values hold good for cuts up to 2mm deep, over 2mm the cutting speed should be reduced by 10 - 20%.

<sup>1)</sup> SS = high speed steel    S<sub>1</sub> H<sub>1</sub> G<sub>1</sub> = tipped tools    E = Cutting emulsion    P = paraffin    L = air

Workpiece material	Tensile strength in kp/mm <sup>2</sup>	<sup>1)</sup> Tool	Cutting angle clearance/top		Feed in mm/rev.				Coolant and Lubricant	
			$\alpha^\circ$	$\gamma^\circ$	0,1	0,2	0,4	0,8	Roughing	Finishing
					cutting speed v m/min					
Steel St 34, St 37, St 42	up to 50	SS	8	14		60	45	34	E	E or P
		S <sub>1</sub>	5	10	280	236	200	170		
St 50, St 60	50...70	SS	8	14		44	32	24	E	E or P
		S <sub>1</sub>	5	10	240	205	175	145		
St 70	70...85	SS	8	14		32	24	18	E	E or P
		S <sub>1</sub>	5	10	200	170	132	106		
Cast steel	50...70	SS	8	10		34	25	19	E	dry
		S <sub>1</sub>	5	6	118	100	85	71		
Alloyed steel	85...100	SS	8	10		24	17	12	E	E or P
		S <sub>1</sub>	5	6	150	118	95	75		
Mn-Steel, Cr-Ni-steel, Cr-Mo-steel	100...140	SS	8	6		16	11	8	E	E or P
		S <sub>1</sub>	5	6	95	75	60	50		
other alloyed steels	140...180	SS	8	6		9,5	6		E	E or P
		S <sub>1</sub>	5	6	60	48	38	32		
Tool steel	150...180	SS	8	6					E	Colza oil or P
		S <sub>1</sub>	5	6	50	40	32	27		
C.I.20,C.I.25	hardness Brinell 200...250	SS	8	0		32	18	13	dry or E	dry
		H <sub>1</sub>	5	0	106	90	75	63		
Copper alloys	hardness Brinell 80...120	SS	8	0		125	85	56	dry, E or L	dry
		G <sub>1</sub>	5	6	600	530	450	400		
Cast bronze		SS	8	0		63	53	43	E or L	dry
		G <sub>1</sub>	5	6	355	280	236	200		
Light alloys aluminium		SS	12	30		400	300	200	E or P	E or P
		G <sub>1</sub>	12	30	1320	1120	950	850		
Aluminium alloys (11...13%Si)		SS	12	18		100	67	45	E	Oil S II or P
		G <sub>1</sub>	12	18	224	190	160	140		
Magnesium alloys*		SS	8	6		1000	900	800	dry or with non-combustible oil	dry or with non-combustible oil
		G <sub>1</sub>	5	6	1800	1500	1250	1060		
Platics and hard rubber		SS	12	10					dry	dry
		G <sub>1</sub>	12	10	300	280	250	224		
Bakelite, Novotext, Pertinax hard plastic		SS	12	14					dry	dry
		G <sub>1</sub>	12	14	280	212	170	132		

\* Do not use with water or water mixtures (DANGER OF FIRE!)


**Circuit Diagrams**

**Electrical Equipments**


**Connection Scheme**

# Standard-Electric Version

## Wiring diagram -- single-phase



## Wiring diagram -- three-phase



I) Electrical Equipment Standard-Electric  
Version COMPACT 10

- b1 Main motor switch
- k1 Condenser main motor (only single phase)
- x1 Clamping strip
- m1 Main motor
- b5 Motor switch vertical unit
- b6 Motor switch coolant pump
- b7 Switch machine lamp
- h1 Machine lamp
- k2 Condenser vertical motor
- k3 Condenser coolant pump
- m2 Motor vertical unit
- m3 Motor coolant pump

} Accessories

SINGLE-PHASE CONNECTION

X1 Clamping strip

Main motor

- L1(1) Phase R
- N(2) Neutral wire
- PE Grounding wire S1  
(connected to  
grounding strip)

Vertical unit

- 3 Phase R (wire no. 1)
- 4 Phase S (wire no. 2)
- 5 Phase T (wire no. 3)
- 6 Condenser vertical  
unit
- 7 Condenser vertical  
unit

Coolant pump

- 8 Phase R
- 9 Neutral wire
- 10

Machine lamp

- 11 Phase R
- 12 Neutral wire N

Note: the grounding wires are  
connected to the grounding  
strip.

THREE-PHASE CONNECTION

X1 Clamping strip

Main motor

- L1(1) Phase R
- L2(2) Phase S
- L3(3) Phase T
- N(4) Neutral wire N
- PE Grounding wire S1  
(connected to  
grounding strip)

Vertical unit

- 5 Phase R (wire no. 1)
- 6 Phase S (wire no. 2)
- 7 Phase T (wire no. 3)

Coolant pump

- 8 Phase R
- 9 Phase S
- 10 Phase T


Machine lamp

- 11 Phase R
- 12 Neutral wire N


Note: the grounding wires are  
connected to the grounding  
strip.

# VDE-Electric Version

## Wiring diagram – single-phase



## Wiring diagram – three-phase



II) Electrical Equipment VDE-Electric Version  
COMPACT 10

- a1 Main and emergency-off switch with low-volt release (c1 - main relay)
  - b1 Main motor switch
  - k1 Condenser main motor (only single phase)
  - x1 Clamping strip
  - m1 Main motor
  - b5 Motor switch vertical unit
  - b6 Motor switch coolant pump
  - b7 Switch machine lamp
  - h1 Machine lamp
  - k2 Condenser vertical motor
  - k3 Condenser coolant pump
  - m2 Motor vertical unit
  - m3 Motor coolant pump
- } Accessories

57

SINGLE-PHASE CONNECTION

X1 Clamping strip

Main motor

- L1(1) Phase R
- N(2) Neutral wire
- PE Grounding wire S1  
(connected to grounding strip)

Vertical unit

- 3 Phase R (wire no. 1)
- 4 Phase S (wire no. 2)
- 5 Phase T (wire no. 3)
- 6 Condenser vertical unit
- 7 Condenser vertical unit

Coolant pump

- 8 Phase R
- 9 Neutral wire
- 10

Machine lamp

- 11 Phase R
- 12 Neutral wire N

Note: the grounding wires are connected to the grounding strip.

THREE-PHASE CONNECTION

X1 Clamping strip

Main motor

- L1(1) Phase R
- L2(2) Phase S
- L3(3) Phase T
- N(4) Neutral wire N
- PE Grounding wire S1  
(connected to grounding strip)

Vertical unit

- 5 Phase R (wire no. 1)
- 6 Phase S (wire no. 2)
- 7 Phase T (wire no. 3)

Coolant pump

- 8 Phase R
- 9 Phase S
- 10 Phase T


Machine lamp

- 11 Phase R
- 12 Neutral wire N


Note: the grounding wires are connected to the grounding strip.

# VDE-Electric Version

## Wiring diagram – single-phase



## Wiring diagram – three-phase







III) Electrical Equipment Special Safety  
Electric Version COMPACT 10

- a1 Main and emergency-off switch with low-volt release (c1 - main relay)
- b1 Main motor switch
- b2 Mushroom off switch
- b3 Micro switch belt cover
- b4 Micro switch chuck guard
- k1 Condenser main motor (only single phase)
- x1 Clamping strip
- m1 Main motor
- b5 Motor switch vertical unit
- b6 Motor switch coolant pump
- b7 Switch machine lamp
- h1 Machine lamp
- k2 Condenser vertical motor
- k3 Condenser coolant pump
- m2 Motor vertical unit
- m3 Motor coolant pump
- m4 Transformer

} Accessories

SINGLE-PHASE CONNECTION

X1 Clamping strip

Main motor

- L1(1) Phase R
- N(2) Neutral wire
- PE Grounding wire S1  
(connected to grounding strip)

Vertical unit

- 3 Phase R (wire no. 1)
- 4 Phase S (wire no. 2)
- 5 Phase T (wire no. 3)
- 6 Condenser vertical unit
- 7 Condenser vertical unit

Coolant pump

- 8 Phase R
- 9 Neutral wire
- 10

Machine lamp

- 11 Phase R
- 12 Neutral wire N

Note: the grounding wires are connected to the grounding strip.

THREE-PHASE CONNECTION

X1 Clamping strip

Main motor

- L1(1) Phase R
- L2(2) Phase S
- L3(3) Phase T
- N(4) Neutral wire N
- PE Grounding wire S1  
(connected to grounding strip)

Vertical unit

- 5 Phase R (wire no. 1)
- 6 Phase S (wire no. 2)
- 7 Phase T (wire no. 3)

Coolant pump

- 8 Phase R
- 9 Phase S
- 10 Phase T

Machine lamp

- 11 Phase R
- 12 Neutral wire N

Note: the grounding wires are connected to the grounding strip.

### Switching Scheme COMPACT 10



Main switch

a1	R U	S V	T W	13 14
0	—	—	—	—
1	x	x	x	x



Main switch (only valid for A13180 + A13181)

a1	L1 U	L2 V	L3 W	1 2	3 4	5 6
0	—	—	—	—	—	—
1	x	x	x	x	x	x

Motor switch single phase

b1	1 2	3 4	5 6	7 8	9 10	11 12
	x	x	x	—	—	x
0	—	—	—	—	—	—
	x	x	—	x	x	—

Motor switch three phase

b1	1 2	3 4	5 6	7 8	9 10
	x	—	—	x	x
0	—	—	—	—	—
	—	x	x	—	x